



M/V J. W. WESTCOTT II in drydock following salvage. Note tires attached to the rail. Photo taken on November 8, 2001.



Starboard side forward of J. W. WESTCOTT II. There are two tires shown in this view. The third tire was removed and lost during salvage. There are two more tires on the starboard side, identical to the port side. Photo taken on November 8, 2001.